

Part I
Performa for the Safety of School Building
(To be filled by the Head of School / Institute)

1. Name of the school
2. Location
3. Plot Area
4. Plinth Area
5. Number of story
6. Year of construction of building
7. Supervision of qualified engineer
The following Details may be given
 - A) Name of the engineer
 - B) Address
 - C) Set of construction drawings used in the construction if available
 - D) Name of the Architect
8. Whether the building has been constructed for the purpose of:
 - a) School (Yes/No)
 - b) Residential purpose and converted for use as a School (Yes/No)
9. Material; used for the Roof:
 - a) R.C.C. Slabs (Yes/No)
 - b) R.S. Joist and Battens (Yes/No)
 - c) Wooden Joist and Battens (Yes/No)
10. Material; used Walls:
 - a) Mud Mortar (Yes/No)
 - b) Cement Mortar (Yes/No)
 - c) Plaster (i) Lime Mortar (Yes/No)
(ii) Cement Mortar (Yes/No)
11. Flooring:
 - a) Conglomerate (Yes/No)
 - b) Terrazzo (Yes/No)
 - c) Brick Paving (Yes/No)
12. Detailed Drawing indicating dimensions of the rooms along with size and location of doors and windows

Eastwood International School
Raikot Road, Mullanpur

16-Canal, 12-Marla

12,118 Sq Ft.

One

2002

Narinder Singh

1777, Maharaj Nagar, Adj P.A.U, Ludhiana

Yes

Ranjodh Singh (Habitat Architects)

School

No

Yes

No

No

No

Yes

No

Yes

Yes

No

No

Yes

Damjit
 Chairman
 Eastwood International School
 MULLANPUR (Ludhiana)

Ananddeep Kaur
 Principal 25/4/23
 Eastwood International School
 MULLANPUR (Ludhiana)

Ananddeep Kaur
 Principal 5/19/23
 Eastwood International School
 MULLANPUR (Ludhiana)

Part II

(To be filled by S.D.E of P.W.D B.& R Department)

I have visited the above mentioned school 08/03/2023 and have visually inspected it from all angles of safety and I found it fit for normal use as school building.

In case any addition / alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified engineer and this certificate may again be obtained after the completion of work from the undersigned.

In case the building is affected by flood or if there is settlement of walls/foundations of caves of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.

This building can be safely occupied for normal use upto 31/03/2024
(indicate year upto which it can be used)

Sub Divisional Engineer
Constn. Sub Division No.3,
P.W.D. B & R Br., Ludhiana.

[Signature]
28

ਨੰਬਰ:- 45-46

ਮਿਤੀ:- 08/03/23

✓ ਪ੍ਰਿੰਸੀਪਲ EASTWOOD INTERNATIONAL SCHOOL MULLANPUR LUDHIANA ਜੀ ਨੂੰ
ਸੂਚਨਾ ਅਤੇ ਜਾਣਕਾਰੀ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।

2. ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ. 1, ਲੇ.ਨਿ.ਵਿ., ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਲੁਧਿਆਣਾ ਜੀ ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਲੋੜੀਂਦੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

[Signature]
Principal 5/9/23
Eastwood International School
MULLANPUR (Ludhiana)

Sub Divisional Engineer
Constn. Sub Division No.3,
P.W.D. B & R Br., Ludhiana.

[Signature]